



Straight shank form drills and reamers are available for machining Sun cavities.

- NOTES:**
- Drill Angle at all steps, 120 degrees included
  - Two Flutes
  - Radius notch thinned point
  - Recommended for use on ductile iron.