



Straight shank form drills and reamers are available for machining Sun cavities.

- NOTES:**
- Drill Angle at all steps, 120 degrees included
 - Two Flutes
 - Radius notch thinned point
 - Recommended for use on ductile iron.