



Scaled 2:1

Dimensions are for reference only. in (mm)

Straight shank form drills and reamers are available for machining Sun cavities.

- NOTES:**
- Six Flutes
 - Recommended for use on ductile iron.